



Market Power & Utilities

Challenge

Two pinhole leaks had developed from internal corrosion in a 36" surge vessel at a natural gas facility. Replacement would be costly and require excessive downtime.

Engineered Solution

The engineer wanted a long-term solution other than replacement. HydraWrap was the selected repair method.

Scope

Precured repair patches were used to cover the pinholes. The surface was then prepared, coated in primer, and wrapped to HydraTech's specifications with the carbon fiber fabric.

Solution

HydraWrap eliminated the pinhole leaks more cost-effectively than replacement. HydraWrap rehabilitated this aging system and will prevent further corrosion and the formation of additional pinholes.







HydraTech Engineered Products, LLC
HydraTech Field Services, LLC
10448 Chester Road, Cincinnati, Ohio 45215 Phone: (513) 827-9169 Fax: (513) 827-9171
https://hydratechllc.com

https://hydratechllc.com/services/field-services/