



Market Waste Water

Challenge

A reducing elbow at a wastewater treatment plant was experiencing sporadic leaking and small holes had formed in the carbon steel.

Engineered Solution

Due to the location of the fitting and the overall expenses of replacement, HydraWrap was selected to rehabilitate and repair the reducing elbow.

Scope

The surface was prepared from flange to flange of the elbow. Primer was applied, followed by four layers of HydraWrap. The repair was completed ahead of schedule.

Solution

HydraWrap proved to be a time-efficient and cost-effective repair that will greatly extend the operational life of this elbow.





